

12



M8x50

=14

13



A8

=28

14



M8

=28


20



M8x60

=14

28



L=920


=7

44



M8

=28



Ø8/Ø12x120

