





































<p>8</p>  <p>M6x20</p> <p>=16</p>	<p>9</p>  <p>M6x50</p> <p>=12</p>	<p>11</p>  <p>M6x60</p> <p>=20</p>	<p>12</p>  <p>M8x50</p> <p>=8</p> <hr/> <p>51</p>  <p>M8x40</p> <p>=4</p>	<p>13</p>  <p>A8</p> <p>=20</p>	<p>14</p>  <p>M8</p> <p>=20</p>	<p>15</p>  <p>M8</p> <p>=6</p>	<p>20</p>  <p>M8x60</p> <p>=6</p>	<p>21</p>  <p>ø10</p> <p>=14</p>
<p>22</p>  <p>ø6x80</p> <p>=14</p>	<p>28</p>  <p>L=720</p> <p>=3</p>	<p>29</p>  <p>A6</p> <p>=32</p>	<p>30</p>  <p>M6</p> <p>=32</p>	<p>31</p>  <p>M6</p> <p>=32</p>	<p>32</p>  <p>=1</p>	<p>33</p>  <p>=1</p>	<p>34</p>  <p>=2</p>	<p>35</p>  <p>L=995</p> <p>=4</p>
<p>36</p>  <p>=2</p>	<p>37</p>  <p>=4</p>	<p>38</p>  <p>L=800</p> <p>=2</p>	<p>39</p>  <p>L=795</p> <p>=10</p>	<p>40a</p>  <p>L=750</p> <p>=1</p>	<p>40b</p>  <p>L=750</p> <p>=1</p>	<p>41</p>  <p>=1</p>	<p>42</p>  <p>=1</p>	<p>43</p>  <p>M8x80</p> <p>=2</p>
<p>44</p>  <p>M8</p> <p>=14</p>	<p>46</p>  <p>30 40</p> <p>=4</p>	<p>47</p>  <p>20 30</p> <p>=20</p>	<p>48</p>  <p>=2</p>	<p>49</p>  <p>=2</p>	<p>50</p>  <p>ø4,8x16</p> <p>=8</p>	<p>52</p>  <p>Hex5</p> <p>=1</p>	 <p>ø6/ø8</p> <p>ø8/ø12x120</p>	